
From: David Keith <dkeith@anchorage.com>
Sent: Wednesday, June 18, 2014 1:28 PM
To: Leos, Valmichael; Miller, Garyg
Cc: Dave Moreira; Phil Slowiak; Wendell Mears; Andrew Shafer; Holly Samaha; Daleel Nangju
Subject: RE: Fence at San Jacinto River
Attachments: Fence_Damage_20140618.pdf

Gary and Valmichael - the attached shows the fence issues we found this morning. The hole is on the north side, between the main gate and interstate. Also noted an area on the south side where the ring ties from the fabric to the poles are missing. See attached photos. We are working with the fencing contractor to get these issues resolved ASAP. We will update you with a schedule as soon as we can confirm things.

Thanks,
David

-----Original Message-----

From: Leos, Valmichael [mailto:Leos.Valmichael@epa.gov]
Sent: Wednesday, June 18, 2014 10:24 AM
To: David Keith; Miller, Garyg
Cc: Dave Moreira; Phil Slowiak; Wendell Mears; Andrew Shafer; Holly Samaha; Daleel Nangju
Subject: RE: Fence at San Jacinto River

Please 'cc' me on this update also.

Valmichael Leos
Federal On-Scene Coordinator (OSC)
1445 Ross Ave (6SF-PE)
Dallas, Texas 75202
Leos.valmichael@epa.gov

214.665.2283 * fax 214.665.2278

-----Original Message-----

From: David Keith [mailto:dkeith@anchorage.com]
Sent: Tuesday, June 17, 2014 4:38 PM
To: Miller, Garyg
Cc: Leos, Valmichael; Dave Moreira; Phil Slowiak; Wendell Mears; Andrew Shafer; Holly Samaha; Daleel Nangju
Subject: Re: Fence at San Jacinto River

Will do Gary. We will get someone out there tomorrow.

Sent from my iPhone

On Jun 17, 2014, at 4:56 PM, "Miller, Garyg" <Miller.Garyg@epa.gov<mailto:Miller.Garyg@epa.gov>> wrote:



David,

Could you have someone go check this out?

Thanks,

Gary Miller
EPA Remedial Project Manager
214-665-8318
miller.garyg@epa.gov<mailto:miller.garyg@epa.gov>

From: Babin, Latrice (PCS) [mailto:Latrice.Babin@pcs.hctx.net]
Sent: Tuesday, June 17, 2014 2:03 PM
To: Miller, Garyg
Subject: FW: Fence at San Jacinto River

The investigator that went out indicated that he removed vegetation that had grown over the hole but would be willing to assist in locating the hole if needed.

Latrice Babin, PhD
HC PCS
713-274-6413

The power of positivity can be positively overwhelming!

From: Babin, Latrice (PCS)
Sent: Monday, June 16, 2014 1:54 PM
To: 'miller.garyg@epa.gov<mailto:miller.garyg@epa.gov>'
Cc: Allen, Bob (PCS); Wheeler, Jennifer (PCS)
Subject: Fence at San Jacinto River

Hello Gary,

We received a complaint today that there was white foam on the river thought to be coming from the Pits as well as a reddish sheen. Someone from our staff was out there around noon today and was able to get right on the capped area due to a hole in the fence on the Monmoth entrance road. He did not see any foam (nor anything else that looked unusual) around the pits but did notice a small amount of foam around the barges in the river.

I am not sure how long the security fencing has been compromised but I did speak with ***** today who indicated that there have been people seen out on the capped area of the pits fishing recently.

Regards,

Latrice Babin, Ph.D.
Environmental Toxins & Special Project Manager Harris County Pollution Control Services Department
101 S. Richey, Suite H
Pasadena, Texas 77506
(713) 274-6413
(713) 274-6475
email latrice.babin@pcs.hctx.net<mailto:latrice.babin@pcs.hctx.net>